

Attorney Docket No. 1419.1059

HE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

Yoshinobu KANEKO

ATTENTION

U.S. Patent No.: 6,971,941

CERTIFICATE OF CORRECTION

Issued: December 6, 2005

BRANCH

For:

ATTACHMENT FOR MOTOR FOR TOY

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents PO Box 1450 Alexandria, VA 22313-1450

Sir:

Patentee respectfully requests that a Certificate of Correction be issued in the subject patent, pursuant to 35 USC § 254 and 37 CFR § 1.322, to correct the error shown on the attached Form PTO-1050. A check in the amount of \$100 to cover the cost of the Certificate is attached.

One or more of the errors shown on the attached Form PTO-1050 is or are within the responsibility of the undersigned; each thereof is of a clerical or typographical nature or of minor character and occurred in good faith, and the correction thereof is consistent with the prosecution record.

Respectfully submitted,

STAAS & HALSEY)LLP

1201 New York Ave, N.W., Suite 700

Washington, D.C. 20005 Telephone: (202) 434-1500 Facsimile: (202) 434-1501

William F. Herbert

Registration No. 31,024 6971941

01 FC:1811

100.00 OP

U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE
Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO: 6,971,941

DATED: December 6, 2005

INVENTOR: Yoshinobu KANEKO

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 7, line 63, delete "on a".

Column 9, line 39, change "is not in" to --can be removed from--.

Column 10, line 31, after "plate" insert --is--.

MAILING ADDRESS OF SENDER: STAAS & HALSEY 1201 New York Avenue, N.W. Suite 700 Washington, DC 20005 PATENT NO. 6,971,941

No. of add'l copies @ 304 per page